DART AEROSPACE LTD	Work Order:	22124
Description: Support Assembly	Part Number:	D3278-041
Dwg: D3278 Rev. A	Qty:	20
		Page 1 of 2

Step	Location	Procedure	D	T D-4:	- Ci
1	DC	Issue Traveler	By	Date	Qty
		TWG NOT REQUIRED PAOU.09.05	14/	05.01.04	20
2	MV	Cut blanks: 2.00" x 1.00" x 2.550" long	$+ \theta$	100.01.04	- ac
		Material: 6061-T6/T651 (QQ-A-200/8) 1.00" thick			
	\	(M6061T6B1.000x02.000)	10		
		Identify for D3278-1 Batch: MIG 241	do	05/01/04	20
3	MV	Cut blanks: 2.00" x 1.00" x 2.550" long		0 3 101107	
		Material: 6061-T6/T651 (QQ-A-200/8) 1.00" thick	Ì		
	\	(M6061T6B1.000x02.000)			
		Identify for D3278-2 Batch: MI6241	W	05/01/64	20
4	MV	Machine D3278-1 as per Folio FA405 and Dwg D3278		3101101	
<u>-</u>		Identify as D3278-1	100	05/01/05	20
5	QC2	Inspect parts as they come off the CNC machine	1		
6	N4) /		En	05/01/05	20
0	MV	Deburr and Tumble	60		
7	QC8	Second check	er	0500	20
	QCO	Second Check	Bro A	1.11.	
8	MV	Machine D3278-2 as per Folio FA405 and Dwg D3278	/ve	05/01/05	20
		Identify as D3278-2	Er	ostalos	2 0
9	QC2	Inspect parts as they come off the CNC machine		02101102	70
			S	05/01/05	2 0
10	M∨	Deburr and Tumble	<u> </u>	C) 10/10/	
		•	Gp	ostolix	70
11	QC8	Second check	- 1	1	_
12	FP	Acid stell and Al II	974	05/01/0x	20
12	1.1	Acid etch and Alodine as per QSI 005 4.1	$\perp V$		70
13	QC5	Inspect work to Step 12	1	05-01-06	20
		mopost from to Otep 12	1///	66 AL -7	10
14	FP	Powder Coat Gloss White (Ref. 4.3.5.1) as per QSI 005 4.3	1111	95 01:07	<u> </u>
			M	05 01 07	11
15	QC3	Inspect Powder Coat	1116	-	10
			my	05-01-07	20
16	GA	Rivet spacers with support as per Dwg D3278. (Note: D3278-1/-2	1		
		are on BOM as material from Steps 2-3)			اما
		Pick: Packing Kit		Ì	46
		Qty Part Number Description Batch	10	.1	1
ŀ		Support 13 32136	1	es-ci-ct	\$ 100 CC
	,	1 D3278-2 Support <u>B∂∂∂∫∂</u> 6 1 D3278-3 Spacer <u>B2/∂</u> 03	My	0 -	
	\	4 MS20426AD3-6 Rivet M 1 5 6 3			1
		111363			
17	QC5	Inspect work to Step 16	1		
J.			BH	05-01-07	20
			· 11.1./	<u></u>	\sim

0

RELEASED

Dart Aerospace Ltd

W/O:							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC inspector
					:		
				-			

NCR: WORK ORDER NON-CONFORMANCE (NCR)						===		
		Description of NC		Corrective Action Section B		Verification	Approval	A
DATE	STEP	Section A			Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector
		Try to fix			OF THE PARTY OF TH			
		:						
		1						
		N,						

Part No:	PAR #:	Fault Category:	NCR:	Yes No	DQA:	Date:
NOTE: Date & initial all entries				QA: N/C	Closed:	Date:

DART AEROSPACE LTD	Work Order:	22126
Description: Support Assembly	Part Number:	D3278-041
Dwg: D3278 Rev. A	Qty:	20
		Page 2 of 2

Step	Location	Procedure	Ву	Date	Qty
18	GA \	Assemble support as per Dwg D3278 Pick: Packing Kit Oty Part Number Description Batch 2 D2230-1 Clamp B2/396 2 AN4-13A Bolt M/59 28 4 AN960JD416 Washer M/53 3 1 2 MS21042L4 Nut (or -4) M/S θ 3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		60,10	
19	QC5	Inspect work to Step 18	D	200-	04
20	ST	Identify and Stock	19	05-01.10 05/01/10	
21	AC	Cost / part 41, 43			20 20
22	DC	Close W/O 40.59 Inspect Level 21	110	05.01.12	20

RevDateChangeRevised ByApprovedA04.04.19New issueKJ/JLM

RELIZASED

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE STEP		PROCEDURE CHANGE			Qty	Approval Mfg / Design Mgr	Approval QC Inspector				
		``.									
	-						3-				
			-				k				

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Approval	Approval		
DATE	STEP	Section A	Design Mar Design Mar		Sign & Date	Section C	Design Mgr	QC Inspector		
05-11-10	18	Stack up telerence 159ce between 2290-1 Clamp and 3278-11-2. Supports, clamp is taght	poorara	- ok to assemble - Engineering to review.		6501-(6	pe 05242	BUK		
		Supports. clamp is taght Detween Supports.		ducys	P65. 4106					

Part No: <u>D3278-041</u>	PAR #:	Fault Category:	_ NCR:	Yes (No) DQA	Date: <u>05/04/2</u> 0
NOTE: Date & initial all entries				QA: N/C Closed:	Date:






DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED	DRAWING NO. REV	. A
7	1	D3278 . SHEET 1 OF	- 3
DATE		TITLE SC/	ALE
04.03.03		SUPPORT ASSEMBLY	VTS
Α	04.03.03	NEW ISSUE	



D3278-041 SUPPORT ASSEMBLY



DART AEROSPACE LTD	Work Order:	22126
Description: Suffort Assembly	Part Number:	P3278-64/(-1)
Inspection Dwg: D3273 Rev: A		Page 1 of 1

	FIRST	ARTICLE IN	SPECTIO	ON CHE	CKLIST .	
	X	First Artic	le	Proto	otype	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
2.439	±0.010	2436	4		vern	
\$ 0.098	+0.005	0098	~		iero	
6.365	±8.010	C 370	<u> </u>		rein	
0.615	±0.010	0.670			mic	
0.250	+0.00	0.252	س		un	
1.480	+0.00	1.478	/		vern	
R. 0.125	10.0/6	0.125			R.G	
0.175	-0.010	0.122			nic	
R. 0.400	+0.010	0.400			2.6	
1.980	+0.010	1.984			1-2" nie	
Q. 0.13	=0.030	0.130			R.G	
9 0.257	+0:005	0.257			vern	
R. O.375	+0.010	0.375			R. 67	
0.075		0.875			vern	
0-500	+0.010	0.502	<u> </u>		vero.	·
1.720	±0.010	1.725	~		ven	-
8.125	±0-010	0.129			nie	
R. O. 125	to:010	D. 175			RG	
	<i>C</i> ?				,T ,et	
•			y :			
		•				
Weasured by:	Er I	Audited by:	ind	Pi	ototype Appro	oval:
Date: c	stofes (Date:	35/01/	06	D	ate: U/A

Weası	ired by:	Er	Audited by:	and	Prototype A	oproval:	.[]^
	Date:	colo fos	Date:	05/01/06	·	Date:	UM
Rev	Date	Change		*		Revised by	Approved
_ A		New Issue				KJ/JLM	

DART AEROSPACE LTD	Work Order: 72/26
Description: Support Assembly	Part Number: 73278-041 (-2)
Inspection Dwg: D3278 Rev: A	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

	>	First Artic	le	Proto	otype	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
2439	+0.00	2439			Vera	
\$ 0.098	+0.005	0.058			Mic	
0.365	+0.010	0.367			MIC	
0.615	±0.010	0.620			Mic	
0750	10.00	0.220			vero	
1.480	10.010	1.478	/		vern	
l.0.125	+0.010	0-125			l Gr	
6.125	+8.010	6.130	/	· · · · · · · · · · · · · · · · · · ·	MIC	
R 0.400	+0.010	0.400	•		R. G1	
1.980	±0.010	1.984			1-Zumic	
R 0.13	to.030	0./3			2.67	4
\$ 0.257	to 005	0.257			vera	
R. 0.375	士0.010	0.375			RG	
0.875	+ 0.010	0.875			vern	And the state of t
0.500	+0.010	0.500			ven	er Procedition of the Control of the
1.720	+0.010	1.720	~		vern	
0.125	±0.010	0.130	-		MIC.	
R. O. 125	+ a.010	0-125	_		R.G	·
					. 7	
			ş - g			

Measured by:	Audited by: 902	Prototype Approval:	, () A
Date: 25/01/6	Date: 05/01/05	Date:	WW
	T,		

Rev	Date	Change	Revised by	Approved
A	i i	New Issue	KJ/JLM	

Job Costing Report

Dart Aerospace Ltd. Hawkesbury

Dec 21, 2004 08:33 am

Work Order No : 0022126
Project Name : D3278-04

Project Name : D3278-041
Project For : WK452

Work Order Type : Main
Main WO Number :

House Part Number: D3278-041
Description: Support Assembly

Manufactured : Yes

Amount Req'd: 20 Amount Done: 0

Start Date : 12-21-04 Est Finish Date : 12-21-04

Act Finish Date :

Drawings Reqd : No
Ok for Approval :

Approval Rec'd :

Department Code:

Burden Flags : NNNNNNN WO Status : Open

Invoice State : Not Invoiced

Invoice Date :

Invoice Number :

Invoice Amount: 0.00

Order Entry No :

OE Value : 0.00

Est Margin : 0.000% Actual Margin : 0.000%

\$0 Posted to Finished Goods

		Estimated	Actual	Var. %	Posted	To Post
Material Cost	===	0.00	0.00	0.00	0.00	0.00
Engineering Hours	:	0.00	0.00	0.00	0.00	•
Engineering Cost	:	0.00	0.00	0.00	0.00	0.00
Production Hours	:	0.00	0.00	0.00		
Production Cost	:	0.00	0.00	0.00	0.00	0.00
Packaging Hours	:	0.00	0.00	0.00		
Packaging Cost	:	0.00	0.00	0.00	0.00	0.00
OverHead Hours	:	0.00	0.00	0.00		
OverHead Cost:	:	0.00	0.00	0.00	0.00	0.00
CNC Hours	:	0.00	0.00	0.00	· -	,
CNC	:	0.00	0.00	0.00	. 0.004	0.00
Misc. Hours	.:	0.00	0.00	0.00		
Misc.	:	0.00	0.00	0.00	<u>⊈</u> 0.00	0.00
·		========	========	====== '	*	
Burden	:	0.00	0.00	0.00		•
		========	=======	======		
Total Cost	:	0.00	0.00	0.00		
Margin	:	0.000	0.000			
Selling Cost	:	0.00	0.00			•

Estimated Actual Labour Hrs/Amount Done : 0.00 0.00 Profits/(Loss) : 0.00 0.00